



产品（黄光）制程




1) Vapor prime




2) Spin coat



3) Soft bake




4) Alignment
and Exposure



5) Post-exposure
bake



6) Develop



7) Hard bake



8) Develop inspect

